

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION I  
J.F.K. FEDERAL BUILDING, BOSTON, MA 02203-2211

MEMORANDUM

DATE: December 10, 1990

SUBJ: Draft SSI Comments  
Bridgeport Name Plate Inc.  
Monroe, Connecticut  
TDD No. F1-8911-01  
CERCLIS No. CTD011184272

FROM: Jane Anderson *JMA*  
CT Site Assessment Coordinator

THRU: Don Smith *DS*  
FIT RPO

TO: John Weiss, NUS/FIT  
SSIGL



SDMS DocID 584754

Pg 2, par 1 - Is the property still owned by Bridgeport Name Plate Inc.?

Table 3 - The population served by the Lakeville well and Stepney should be revised if the wells also serve residents outside of Newtown and Monroe. Has the percentage of water supplied by these two wells in the system been calculated by BHC and is this information known? Please indicate an average proportionment over the year if possible. Another column should be added which indicates well type, depth and screen interval, if known.

Table 6 - It appears that some semi-volatile organic compounds and endosulfan sulfate were left out of the table.

Contact P + M Realty Inc. and the Monroe Department of Health to try to determine whether the water supply wells have ever been sampled. Although hydraulically upgradient of the known source areas, the pump may draw potential contaminants towards the wells. All efforts should be made to locate private wells before sampling.

EPA concurs with the recommendation for a Listing Site Inspection.